


| OCCUPANCY | EXTERIOR | FLOOR | AREA | CONST | VALUE |
|--|--|-------------------------|------------|-------|---------|
| <input checked="" type="checkbox"/> SF <input type="checkbox"/> DU <input type="checkbox"/> TR | <input type="checkbox"/> WOOD | 1 | 1760 | FR | 276,250 |
| <input type="checkbox"/> CONVERSION | <input checked="" type="checkbox"/> STUCCO | 2ND | 1760 | FR | 82,880 |
| BUILDING TYPE | <input type="checkbox"/> ALM/VYNL | | | | |
| <input type="checkbox"/> MOBILE HOME | <input type="checkbox"/> CONC BLK | | | | |
| <input type="checkbox"/> BI/TR LEVEL | <input type="checkbox"/> METAL | | | | |
| <input type="checkbox"/> MOD/MAN | <input type="checkbox"/> BRICK | | | | |
| <input type="checkbox"/> _____ | <input type="checkbox"/> STONE | | | | |
| ROOFING | ROOF TYPE | | | | |
| <input type="checkbox"/> METAL | <input checked="" type="checkbox"/> GABLE | | | | |
| <input type="checkbox"/> SLT/TLE | <input type="checkbox"/> HIP | | | | |
| <input checked="" type="checkbox"/> SHINGLES | <input type="checkbox"/> GAMBREL | | | | |
| <input type="checkbox"/> SHAKES | <input type="checkbox"/> MANSARD | | | | |
| <input type="checkbox"/> COMPOSITE | <input type="checkbox"/> FLAT | | | | |
| FLOORS | B 1 2 3 U | BSMT | 1760 | | 25,340 |
| CONCRETE | <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> | SUBTOTAL | | | 384,470 |
| WOOD | <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> | MULTI-FAMILY # | 0 | | 0 |
| TILE/COMPO | <input type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> | BUILDING TYPE | 100% | | 0 |
| CARPET | <input type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> | BSMT FINISH | 0 S.F. | | 0 |
| INT. FINISH | B 1 2 3 U | FIREPLACE # | 1 | | 3,100 |
| PLASTER/DW | <input type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> | HEATING | 0 S.F. | | 0 |
| PANELING | <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> | AIR COND | 3,520 S.F. | | 7,600 |
| UNFINISHED | <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> | PLUMBING # | 5 | | 6,000 |
| ACCOMMODATIONS | | GARAGES & CARPORTS | | | 17,200 |
| # OF ROOMS | | EXTRA FEATURES | | | 12,680 |
| BEDROOMS | | SUBTOTAL | | | 431,050 |
| FIREPLACES | | GRADE FACTOR | | | 130 % |
| HEAT & AC | B 1 2 3 U | UNADJUSTED VALUE | | | 560,370 |
| NO HEAT | <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> | FACTOR | | | 100 % |
| CTRL HEAT | <input type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> | | | | |
| HW/STEAM | <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> | | | | |
| ELECTRIC | <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> | | | | |
| HEAT PUMP | <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> | | | | |
| FLR/WALL | <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> | | | | |
| STVE/SPCE | <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> | | | | |
| GEOHERMAL | <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> | | | | |
| OUTSIDE | <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> | | | | |
| CTRL A/C | <input type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> | | | | |
| PLUMBING | BASE <input checked="" type="checkbox"/> | | | | |
| X FULL BATH | | | | | |
| X HALF BATH | | | | | |
| X FIXTURES | | | | | |



| OCCUPANCY | ST.HT | SIZE | AREA | GRADE | PRICE | AGE | REMD | CND | UNADJ VAL | PHYS | PHYS VAL | FUNC | TRUE VAL |
|-----------|-------|------|-------|-------|-------|------|------|-----|-----------|------|----------|------|----------|
| DWELLING | 2 | SK | 3,520 | B | | 2006 | | A | 560,370 | 18 | 459,500 | | 381,390 |
| 1 | | | | | | | | | | | | | |
| 2 | | | | | | | | | | | | | |
| 3 | | | | | | | | | | | | | |
| 4 | | | | | | | | | | | | | |
| 5 | | | | | | | | | | | | | |
| 6 | | | | | | | | | | | | | |
| 7 | | | | | | | | | | | | | |
| 8 | | | | | | | | | | | | | |
| 9 | | | | | | | | | | | | | |
| 10 | | | | | | | | | | | | | |
| 11 | | | | | | | | | | | | | |

39-0029010.0770

TOTAL 381,390

COMMENTS
 5 LEVEL SPLIT
 (288SF CATH=\$10,370),(24SF OFP=\$290),(168SF OFP=\$2,020),(288SF AGFF=\$6,840),(436SF AGFF=\$10,360)
 Dwelling has an Economic Factor of 83%